Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/20002BR0171/1
Work Order Type: Weatherization

Audit Name: 20002BR0171

CLIENT INFORMATION

Client Name: Address:

Client ID: 20002BR0171

Alt. Client ID: Bradley

<u>AGENCY INFORMATION</u>

Agency: Bradley-Cleveland Community Services Agency Agency Phone: (423) 479-4111

Address: P.O. Box 3297, 155 Sixth Street, S.E. **Fax:** (423) 479-4113

Cleveland, TN 37320 *Email Address:*

Agency Contact: Daugherty, Sam Work Phone:

Cell Phone: (865) 207-0215

Email Address: samdaugherty@charter.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

brick house w/gas heat Certified Firm/Renovator Required

Measures

•	Measure Lead	d Safety APA/RRP			Componer	nts		ı	Inspected
Comment				Fatimata	. 1	Actual			
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
7	Health and Safety Items	Lead safe pracice							
C	Other Detail								
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Magazira 4 Infili	wation Dadate			Componen				Inspected
		ration Redctn			Componer	แร		1	mspecieu
C	'ammant mactic (
		vents and 1 return, cau							
	nail pan	eling @ left side of door	to addition	n, seal	8" hole in v	vall left of	door to		
	nail pan addition		to addition	n, seal	8" hole in v	vall left of	door to		
	nail pan addition	eling @ left side of door ,-old firplace vent, seal p	to addition	n, seal	8" hole in v	vall left of bing in ha	door to		
	nail pan addition off dmb	eling @ left side of door ,-old firplace vent, seal p	to addition	n, seal	8" hole in v , seal plum	vall left of bing in ha	door to)	Total
#	nail pan addition off dmbi	eling @ left side of door ,-old firplace vent, seal p r, d-1 w/s, d-2 w/s	to additior olumbing a	n, seal t dryer	8" hole in v , seal plum!	vall left of bing in ha	door to	Actual	Total
#	nail pan addition off dmb	eling @ left side of door ,-old firplace vent, seal p r, d-1 w/s, d-2 w/s Description / Comment	to addition olumbing a <i>Unit</i> s	n, seal t dryer Qty	8" hole in v , seal plum!	vall left of bing in ha	door to	Actual	Total
# 10	nail pan addition off dmbi	eling @ left side of door ,-old firplace vent, seal p r, d-1 w/s, d-2 w/s Description / Comment	to addition olumbing a <i>Unit</i> s	n, seal t dryer Qty	8" hole in v , seal plum!	vall left of bing in ha	door to	Actual	Total
# 10	nail pan addition off dmbi Material / Labor Miscellaneous Supplies	eling @ left side of door ,-old firplace vent, seal p r, d-1 w/s, d-2 w/s Description / Comment	to addition olumbing a <i>Unit</i> s	n, seal t dryer Qty	8" hole in v , seal plum!	vall left of bing in ha	door to	Actual	Total
# 10	nail pan addition off dmbi Material / Labor Miscellaneous Supplies	eling @ left side of door ,-old firplace vent, seal p r, d-1 w/s, d-2 w/s Description / Comment	to addition olumbing a <i>Unit</i> s	n, seal t dryer Qty	8" hole in v , seal plum!	vall left of bing in ha	door to	Actual	Total
# 10	nail pan addition off dmbi Material / Labor Miscellaneous Supplies	eling @ left side of door ,-old firplace vent, seal p r, d-1 w/s, d-2 w/s Description / Comment	to addition olumbing a units	n, seal t dryer Qty 1	8" hole in v , seal plum!	vall left of bing in ha	door to alf bath	Actual	Total
# 10	nail pan addition off dmbi Material / Labor Miscellaneous Supplies	eling @ left side of door ,-old firplace vent, seal p r, d-1 w/s, d-2 w/s Description / Comment	to addition olumbing a units	n, seal t dryer Qty 1	8" hole in v , seal pluml Estimated Unit Cost	vall left of bing in ha	door to alf bath	Actual Unit Cost	Total
# 10	nail pan addition off dmbi Material / Labor Miscellaneous Supplies Other Detail	eling @ left side of door ,-old firplace vent, seal p r, d-1 w/s, d-2 w/s Description / Comment	to addition olumbing a units	n, seal t dryer Qty 1	8" hole in v , seal pluml Estimated Unit Cost	vall left of bing in ha	door to alf bath	Actual Unit Cost	Total
# 10	nail pan addition off dmbi Material / Labor Miscellaneous Supplies Other Detail	eling @ left side of door ,-old firplace vent, seal p r, d-1 w/s, d-2 w/s Description / Comment	to addition olumbing a units	n, seal t dryer Qty 1	8" hole in v , seal pluml Estimated Unit Cost	vall left of bing in ha	door to alf bath	Actual Unit Cost	Total

Page 2 of 5

	Measure 2 DW	/H Tank Insulation			Componer	nts			Inspected
Ŭ					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
C	Other Detail]			1		
L]		
				Measur	e Sub Total:] .	Sub Total:	
		or Ins. R-19 19 batts secure w/wire 22	200sqft		Componer Estimated			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	2200		TOTAL	Qty	Omit Cost	Total
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Report Run On: 5/27/2010

Measure 4 CO	Monitor is Needed			Componen	ts			Inspected
Comment 2 each	1 in Ir, 1 in hall							
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	CO monitor	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								
Macaura F. Find	lana a sa Maratina a (Oladi	haa Dunaw		Camananan				Inspector
	mproper Venting (Clot) ement by Linear Foot. R	-			tal			Inspected
Comment Replace	ement by Linear Foot. R	eplac e vir	nyl hos	e w/flex met	tal /	Qty	Actual	
	ement by Linear Foot. R Description / Comment	-		e w/flex met	tal	Qty		Inspected Total
Comment Replace # Material / Labor 1 Health and Safety	ement by Linear Foot. R Description / Comment	eplac e vir	onyl hos	e w/flex met	tal /	Qty	Actual	
Comment Replace # Material / Labor 1 Health and Safety Items	ement by Linear Foot. R Description / Comment Equipment	eplac e vir <i>Units</i> Each	Qty 1	e w/flex met	tal /	Qty	Actual	
Comment Replace# Material / Labor1 Health and Safety Items2 Labor	ement by Linear Foot. R Description / Comment Equipment	eplac e vir <i>Units</i> Each	Qty 1	e w/flex met	tal /	Qty	Actual	
Comment Replace# Material / Labor1 Health and Safety Items2 Labor	ement by Linear Foot. R Description / Comment Equipment	eplac e vir <i>Units</i> Each	Qty 1	e w/flex met	tal /	Qty	Actual	
Comment Replace# Material / Labor1 Health and Safety Items2 Labor	ement by Linear Foot. R Description / Comment Equipment	eplac e vir Units Each Each	Qty 1	e w/flex met	tal /		Actual	
Comment Replace# Material / Labor1 Health and Safety Items2 Labor	ement by Linear Foot. R Description / Comment Equipment	eplac e vir Units Each Each	Qty 1	e w/flex met Estimated Unit Cost	tal /		Actual Unit Cost	
# Material / Labor 1 Health and Safety Items 2 Labor Other Detail	ement by Linear Foot. R Description / Comment Equipment	eplac e vir Units Each Each	Qty 1	e w/flex met Estimated Unit Cost	tal /		Actual Unit Cost	

Report Run On: 5/27/2010

	<i>Measur</i> e 6 Smo	ke Detector is Needed			Componen	ts		I	nspected
C	comment replace	the one in the hallway							
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke detector	Each	1					
2	Labor	Labor	Each	1					
C	Other Detail						_		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
L									
			Work Or	der Gra	nd Total:		Gran	d Total:	

Report Run On: 5/27/2010